

CHANGE HISTORY for

- ✓ **DEH-X7800DAB**
- ✓ **DEH-X5900BT**
- ✓ **MVH-X580BT**
- ✓ **MVH-X580DAB**
- ✓ **FH-X730BT**
- ✓ **FH-X840DAB**

Remarks:

- ✓ **Make sure to download the correct firmware file for your region, the European versions (EW or UW model) and US version (*) use a different update file**
(*) In case you have US model, please visit 'pioneerelectronics.com/firmware'
- ✓ **Do NOT install a firmware file which is intended for a different model and or region.**

Ver 8.38 (August, 2018 Update)

- ✓ Fixed the problem that the receiving volume of particular smart phone becomes low when talking on the phone connected to a CD Receiver with BT.
- ✓ Supports Bluetooth playback of some smart phones (Android Ver. 8).

Ver 8.36 (November, 2016 Update)

- ✓ Improve Bluetooth connectivity
- ✓ Improve the performance of iPod Source
- ✓ Improve the performance of USB Source
- ✓ Fix charging from the CD receivers is slow problem
- ✓ Minor bug fixes

Ver 8.27 (June, 2016 Update)

- ✓ Improved Bluetooth connectivity.
- ✓ Improved performance of MTP function.
- ✓ Improved performance of USB Source.
- ✓ Minor bug fixes.