

CHANGE HISTORY for

- ✓ AVH-X5700BT
- ✓ AVH-X4700DVD
- ✓ AVH-X2700BT
- ✓ AVH-X1700DVD

Remarks:

- ✓ Make sure to download the correct firmware file for your region, the European version (EW or UW model) and US version (*) use a different update file (*) In case you have US model, please visit 'pioneerelectronics.com/firmware'
- ✓ Do NOT install a firmware file which is intended for a different region.
- √ The DAB models (AVH-X5700DAB and AVH-X3700DAB) use a different update file, make sure to check that you download the firmware file for your model,.

Ver 8.53 (January, 2019 Update)

- ✓ Corrects a problem in the iPod source where the artwork does not change to match the current track.
- ✓ Corrects a problem with the voice recognition operation via the steering wheel controls.
- ✓ Corrects a problem in iPod source where a track may be skipped when "Short Playback Mode" of MIXTRAX settings is turned on

Ver 8.50 (July, 2016 Update)

- ✓ Add "AppRadioMode Sound" settings to System Menu (*)
- ✓ Fixed incompatibility issues of virtual keyboard with iOS9
- ✓ Improvement of connectivity for MirrorLink
- ✓ Minor bug fixes
 - (*) The AppRadioMode Sound setting can be used to define if the AppradioMode sound should be output from the speakers connected to the AVH product or direct from the Android phone speaker.

Remarks:

- The setting has been implemented as some Android phones cannot output the AppRadioMode sound.
- With an iPhone, the sound is always output from the speakers connected to the unit.



 The setting is available from System settings → Input/Output setting → AppRadioMode sound → AVH/Smartphone)

Ver 8.40 (8 May, 2015 Update)

- ✓ Improved Bluetooth handsfree operation while transferring Phonebook data (AVH-X2700BT and AVH-X5700BT)
- ✓ Minor Bug Fixes

Ver 8.31 (11 February, 2015 Update)

✓ Minor bug fixes.

Ver 8.25 (8 December, 2014 Update)

- ✓ AppRadio Mode via USB improvements.
- ✓ Minor bug fixes.