

AVIC-F310BT - CHANGE HISTORY

Ver. 1.0004

- ✓ Increased Bluetooth microphone sensitivity.

Ver. 1.0003

- ✓ Fixes that in some specific conditions the touch panel is inoperative (display seems frozen)

Ver. 1.0001

- ✓ General UI improvement.
- ✓ Improvement on Eco function via NavGate Feeds.
- ✓ Improvement on "Call POI" function.