

CHANGE HISTORY for

- ✓ AVIC-F60DAB
- ✓ AVIC-F960BT
- ✓ AVIC-F960DAB
- ✓ AVIC-F860BT

Remarks:

- ✓ Do NOT install this firmware to the Camper Van models; AVIC-F860BT-C, AVIC-F960BT-C or AVIC-F960DAB-C ("-C" stands for Camper Van, these models have Firmware version "8.01xxxx", check the update instructions how to display the firmware version)
- ✓ Make sure to download the correct firmware file for your region, the European version (EW model), Russian version (UW model) and US version (*) use a different update file
 - (*) In case you have US model, please visit 'pioneerelectronics.com/firmware'
- ✓ Do NOT install a firmware file which is intended for a different region.

Ver 1.21 (November, 2018 Update)

✓ Improved connectivity with AVIC SYNC

Ver 1.20 (July, 2018 Update)

✓ Improved Apple CarPlay connectivity

Ver 1.15 (July, 2017 Update)

- ✓ Reduce noise when playback iPod
- ✓ Add QWERTY keyboard in AppRadio Mode *UC model only
- ✓ Fix the malfunction at "Artist Alert" event *UC model only

Ver 1.14 (January, 2017 Update)

- ✓ Improve the virtual keyboard problem on iOS 9.x.
- ✓ Fix the incorrect indication of names on the screen at Bluetooth Handsfree mode in Thai.
- ✓ Fix the music display problem on iOS 8 and later.
- ✓ Minor bug fixes

Ver 1.11 (23 November, 2015 Update)

✓ Support for AVICSYNC

REMARK: If you don't intend to use the AVICSYNC features then it is not necessary to install this update.



Ver 1.07 (15 October, 2014 Update)

✓ Minor bug fixes.

Ver 1.06 (2 October, 2014 Update)

- ✓ Apple CarPlay[™] support for iPhone 6 Plus, iPhone 6, iPhone 5s, iPhone 5c, and iPhone 5
- ✓ iTunes® Radio support for iPhone 6 Plus, iPhone 6, iPhone 5s, iPhone 5c, and iPhone 5
- ✓ Support for MPEG-2 playback (support for *.vob files on USB and SD source)
- ✓ Improved Rear view camera support
- ✓ Minor bug fixes.

Ver 1.04 (9 September, 2014 Update)

✓ This firmware will allow the users to purchase Speed Camera data and Optional TMC services from pioneer.naviextras.com

Ver 1.04 (12 August, 2014 Update)

- ✓ This firmware is required to use pioneer.naviextras.com
- ✓ 2nd Camera Switching via 'Map' button
- ✓ Minor bug fixes.