

## **SPH-DA100 - CHANGE HISTORY**

### **Ver 8.30**

- ✓ Support for iPhone 5 and fifth generation iPod touch.

#### **Remarks**

- iPhone 5 compatibility requires the purchase of Pioneer CD-IH202 interface cable kit, Apple® Lightning to Digital AV Adapter, and Apple USB to Lightning cable (each sold separately).
- No need to install this update if you do not own an iPhone 5 or fifth generation iPod touch.

### **Ver 8.17**

- ✓ Support for a new touch panel device
- ✓ Improvement in recognition accuracy when a smartphone is exchanged for a MHL adapter
- ✓ Improvement of reliability of touch panel operation
- ✓ Improvement of the displayed time when operating in rear-view mode
- ✓ Solved a problem which could make that the update process could go wrong

### **Ver 8.15**

- ✓ Rear view camera stability improvements