

# **CHANGE HISTORY FOR SPH-EV0950DAB**

### Ver 1.56 (April, 2024 Update)

✓ Fixed an issue where voice guidance stops midway in smartphone linkage functions.

#### Ver 1.55 (November, 2023 Update)

✓ Fixed an issue where USB video could not be displayed on the rear.

#### Ver 1.54 (July, 2023 Update)

- ✓ Improved WebLink connectivity.
- ✓ Other minor bug fix

#### Ver 1.53 (June, 2023 Update)

✓ Fixed an issue where the WebLink screen would sometimes appear when using other functions when WebLink is linked.

## Ver 1.52 (April, 2023 Update)

- ✓ Fixed an issue that a DAB preset may not be saved correctly
- ✓ Fixed an issue that text information of Digital radio may not be displayed correctly on the Home screen
- ✓ Fixed several issues which may cause a WebLink connection failure
- ✓ Device connectivity improvements

## Ver 1.33 (March, 2023 Update)

✓ Usability enhancements