

## **CHANGE HISTORY for**

AVH-Z5200DAB AVH-Z5200BT AVH-Z3200DAB AVH-Z2200BT

## Ver 8.12 / 18.12 / 28.01 (November, 2019 Update)

✓ Fixed the problem that there is no sound from the rear speakers after finishing a call.

## Ver 8.10 (June, 2019 Update)

- ✓ Improved touch accuracy of external navigation system.
- ✓ Minor bug fixes

## Ver 8.04 (April, 2019 Update)

- ✓ Improved behavior of WebLink
- ✓ Other minor bug-fix