

CHANGE HISTORY for

✓ AVIC-F500BT Updated with CNSD-250FM/EU5

Ver. 4.001000

- Countermeasure for a problem that the navigation unit reboots when receiving specific TMC codes in France