

CHANGE HISTORY for

- ✓ **DEH-X5700BT**
- ✓ **DEH-4700BT**
- ✓ **MVH-X370BT**
- ✓ **FH-X720BT**

Ver A860

- ✓ Solves the problem that the CD Receiver and the Digital Media Receiver don't ring when there is an incoming call with blocked caller ID.